Xylem Water Solutions USA, Inc.
Flygt Products

PRODUCT REPAIR / SERVICE ESTIMATE

Estimate #: R2021-IND-0374 Date: 2/2/2022
Tag #: 4038
JobName: Box Factory

Customer Information

Company Name: GREENFIELD WSTWTR UTLTY
Address
809 S STATE ST

GREENFIELD IN46140

Contact: Nick
Telephone:
Telephone:
Fax:
Email:

Following is an estimate prepared for you regarding the repair of your Flygt pump.

Product Identification

Product Number:
Serial Number: 4NS12M3CF

Model:
Impeller Code:
HP: 0
Volts: 0
Phases: 3

Inspection Information

Inspected By: Sean Hopper

Motor Data: Wire Configuration: U1:Red V1:Black W1:White
Megger to ground: R 0.0 B 0.0 W 0.0
Resistance through cable: RB .37 RW .37 BW .37
Stator Condition: Poor
Shaft Condition: Poor
Oil Condition: Unusable
Inspection Plugs:

Sensors:

- [x] FLS
- [ ] CLS
- [ ] KLIX
- [ ] Bearing
- [x] Cable

Hydraulic: Impeller/Propeller Condition: Poor
Volute Condition: Good

Cable Condition: Good
Cable Length:

PRODUCT REPAIR / SERVICE ESTIMATE

Estimate #: R2021-IND-0374 Date: 2/2/2022
Tag #: 4038
JobName: Box Factory

Hydraulic Type: C
Installation Type: P
Discharge Size:

☐ Control
230v

☐ MFV

Primary Requirement: Media throughout pump

Repair/Service Requirements and remarks

Upon inspection of the pump i found the meg/ohm of the stator to read bad. The oil housing in the pump was full of sand. The seals were out in the pump allowing media to penetrate the stator housing. The rotor has damage and it need to be repaired in order to hold the new seal. The pump needs a new seal and bearing kit. Finally the stator on the pump needs replaced.

Parts, Labor and Other Charges

Parts:

Qty	PartNo	Description	Sell Price	Total Price
1	2K776	Impeller for 15hp	$968.26	$968.26
1	279-2622	3 phase 230v motor	$1.54	$1.54
1	10k181	Seal kit	$1,792.93	$1,792.93
1	4K698	Bearing kit	$297.53	$297.53
1	5K420	O-ring kit	$407.48	$407.48
1	1	Rotor Repair	$2,233.00	$2,233.00
		Total Price		$5,700.74

Labor and Other Charges:

Qty	PartNo	Description	Sell Price	Total Price
10	14-69 00 02A	LABOR,SVC FLYGT,NO TAX Z3-TP MODELS: 3000,7000,8000	$135.00	$1,350.00
1	14-69 00 21C	ENV FEE 11-50HP NO TAX TP ENVIRONMENTAL FEE	$83.00	$83.00

PRODUCT REPAIR / SERVICE ESTIMATE

Estimate #: R2021-IND-0374 Date: 2/2/2022
Tag #: 4038
JobName: Box Factory

1	14-69 00 24A	SHOP SUPPLIES-MEDIUM PUMPS FOR REPAIR	TP MISC SUPPLIES	$61.00	$61.00
		Total Price			$1,494.00

Total Price: $7,194.74

Product Replacement

Product Number:
Cost of New Unit:
Description:
Estimated Delivery: Weeks

Terms

Please note: If additional repair requirements are identified during service, the total cost of your repair may change. Should this occur, we will contact you for approval before proceeding.
A signed Purchase Order or approval below must be received before any repair work can begin.
If repaired unit is not picked up or delivered within 5 days of completion, the repair will be invoiced.

Taxes: The prices quoted above do not include any state, federal, or local sales tax or use taxes. If tax exempt, please provide a copy of your Indiana State ST-105 Form with your order so we are able to update your Xylem Water Solutions USA, Inc. customer file.
Time of delivery: Approx. 3-4 working weeks after receipt of order.
Terms of payment: 100% N30 after invoice date.
Exclusions: This Quote includes only the items listed specified above.
Warranty: Parts used for this repair carry a 12 month warranty.
Validity: This Quote is valid for sixty (60) days.
Inspection Fee: If pump is not repaired following full inspection, a fee may be charged for the inspection.
Changes: This Quote is based on the current design criteria provided to Xylem Water Solutions USA, Inc. Revisions may result in price changes.
The Xylem Water Solutions USA, Inc. North American Terms and Conditions of Sale dated January 2015 incorporated herein apply to this order and is accessible at http://www.xylemwatersolutions.com/scs/usa/en-

PRODUCT REPAIR / SERVICE ESTIMATE

Estimate #: R2021-IND-0374 Date: 2/2/2022
Tag #: 4038
JobName: Box Factory

us/Pages/General-Terms-and-Conditions-of- Sale.aspx . Partial billing will be made on any partial shipments. Equipment returns are subject to approval and possible re-stocking fees. Special order items(i.e. Control Panels, hatch covers) will not be accepted for return.

Thank you for the opportunity to provide this quotation. Please contact us if there are any questions.

Phone:
Fax:

PRODUCT REPAIR / SERVICE ESTIMATE

Estimate #: R2021-IND-0374 Date: 2/2/2022
Tag #: 4038
JobName: Box Factory

Customer Approval

Complete and sign this Approval and return to Xylem Water Solutions USA, Inc with, or in place of, your Purchase Order

I authorize Xylem Water Solutions USA, Inc to proceed for the amount shown above. ☐ Repair ☐ Replacement

Customer Name: _____ Date: _____

Customer Signature: _____ PO #: _____

Ship To: ☐ Will Pick Up ☐ Deliver ☐ Ship To

Ship/Delivery Address: _____

_____

_____

_____

Bill To: _____

_____

_____

_____

Taxable: ☐ Yes ☐ No

Tax Exemption Certificate must be on file or tax will be applied to the invoice.