


Repair Order Receipt

Tennant Sales and Service
701 N Lilac Drive
Minneapolis, MN 55427 USA
(800) 553-8033



Ship To:
ABBOTSFORD CONCRETE PRODUCTS L
3422 MCCALLUM RD
ABBOTSFORD, BC V2S 7W8

Bill To:
ABBOTSFORD CONCRETE PRODUCTS L
3422 MCCALLUM RD
ABBOTSFORD, BC V2S 7W8

M525GM (M525GM/000000000200504182)

Hour Meter: 0
Ship Date: 12/31/1899

Repair Order #: 000303908785

Date: 2/21/2014

Cause code: Breakdown

Problem Description: 525-14123-ONLY 1/2 OF DISPLAY LIGHTS

Contact: BOB LEACH

Phone: 604-852-4967

PO: SIGNED WORK ORDER

Labor/Trips

Date	Part Num	Svc Rep	Description	A/I	Qty/Hrs
2/21/2014	REGLAB	1CT582	Regular Labor	C	1
2/21/2014	TRIP	1CT582	Site Visit	C	1
2/21/2014	MCHWKG	1CT582	Machine tested and running	C	1

Shop Supplies and Tax

Date	Description
2/21/2014	Shop Supplies & Disposables
2/21/2014	Tax

Description of Work Performed

Check for IQAN display not working properly (customer wishes to get hourmeter reading).
Inspect display (only approx 1/2 of the LCD display is working).
Discuss with tech support (display and hourmeter memory are part of the same unit, if replaced hourmeter will show '0').
Attempt to read hourmeter.
Probable but not guaranteed readings are as follows:
Total engine runtime= 63 hours
Eaton Pump runtime= 47 hours
Work runtime = 16 hours
Transit runtime = 1 hour
Visual condition of machine appears to reflect hour meter reading.

Talk to Customer Service to see about machine history:
Machine was produced Sept 29, 2008 and shipped to North America 2 months later. No other history available.
Leave quote for new IQAN module.

Service Representative - JEFF CHESLOCK
Date: 2/21/2014

Customer -
Date: