
Dot Daily Vehicle Inspection Form

Date: July 15, 2024

Driver's Name: Emily Carter

Company Name: Carter Transport LLC

Vehicle Type: Commercial Truck

Vehicle Make/Model: Volvo VNL

Vehicle Year: 2023

License Plate Number: XT4927

Odometer Reading: 112,347

Inspection Checklist

1. Service Brakes, including trailer brake connections

- Working properly

Comments: No issues found.

2. Parking (hand) brake

- Engages and holds vehicle

Comments: Functions as expected.

3. Steering Mechanism

- Operates smoothly

Comments: Steering checked, no problems detected.

4. Lighting Devices and Reflectors

- Headlights, taillights, turn signals, reflectors

Comments: All lighting devices working properly.

5. Tires

- Condition, tread depth, and inflation

Comments: Front tires at 80% tread, rear tires at 75% tread, all tires properly inflated.

6. Horn

- Functional and audible

Comments: Horn loud and clear.

7. Windshield Wipers

- Operate effectively

Comments: Wipers in good condition, fluid level full.

8. Rear Vision Mirrors

- All mirrors present and adjustable

Comments: Mirrors intact and offering clear rear visibility.

9. Coupling Devices (if applicable)

- Secure and free of excessive wear

Comments: Coupling checked, no excessive wear.

10. Wheels and Rims

- Free from cracks and distortions

Comments: Wheels and rims are undamaged.

11. Emergency Equipment

- Fire extinguisher, warning devices for parked vehicles, spare fuses

Comments: All emergency equipment in place and functional.

Additional Remarks:

Comments: The vehicle is in excellent condition, ready for the day's route.

Certification of Inspection

I certify that I have inspected the above vehicle as required by the DOT regulations and have found it to be in satisfactory condition.

Driver's Signature: Emily Carter

Supervisor's Signature: John Adams (if applicable)

Note: This inspection has confirmed that the vehicle meets all necessary DOT standards and is safe for operation. Any issues identified during the inspection have been addressed prior to this report